Qty:

Monday, 19/01/2009 8:34:33 AM

User:

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

: 44879

Estimate Number

: 13732

P.O. Number

Job Number

This Issue : 19/01/2009

: NC

Prsht Rev. First Issue

: //

Type

S.O. No. :

: MACHINED PARTS

Part Number

Due Date

Drawing Name

: D26171 D2617 REV D2

: BUSHING

Drawing Number

: N/A

Project Number Drawing Revision

: D2 Material

20/01/2009

Each

Written By

Previous Run

Checked & Approved By

Comment

: Est Rev:A $\sqrt{09-01-19}$ rev.D2 as per dwg DD verified by:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

M6061T6T0375W058 1.0

6061-T6 RD Tube .375 x.058W



Comment: Qty.:

0.1641 f(s)/Unit

Total: 0.1641 f(s) 6061-T6 Round Bar 1.5"

Material: 6061-T6 (QQ-A-225/8 or QQ-A-200/8 or WW-T-700/6) Ø0.375" tubing x 0.058" wall

(M6061T6T0.375W.058) Batch: 1110271

2.0

3.0

4.0

HARDINGE



Comment: HARDINGE

QC2

Turn as per Folio FA796 and Dwg D2617



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

QC8

SECOND CHECK



Comment: SECOND CHECK



5.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr break all unmarked sharp edges 0.005 to 0.010



09.01.20

Date: User:	Monday, 19/01/2009 8:34:33 AM Linda Lacelle	Process Sheet
Custo	omer: CU-DAR001 Dart Helicopters Ser	rvices Drawing Name: BUSHING
Job Nur	nber: 44879	Part Number: D26171
Job Number		
Seq. #:	Machine Or Operation:	Description :
6.0	QC5	INSPECT WORK TO CURRENT STEP
7.0	DEPARTMENT: INSPECT WORK TO CURRENT HAND FINISHING1	HAND FINISHING RESOURCE #1
8.0	omment: Acid etch and Alodine as pe QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
9.0	pmment: INSPECT POWDER COAT/ PACKAGING 1	CHEMICAL CONVERSION PACKAGING RESOURCE #1
5.0	PACKAGING I	- PACKAGING RESOURCE #1
Co	pmment: PACKAGING RESOURCE #	#1
	Location:	(4 of 20 (20)
10.0	QC21	Final MSPECTION/WIO RELEASE 09/01/20
Co	omment: FINAL INSPECTION/W/O R	
Job Completion		MF 09-01-3

Form: rprocess

Page 2

DART AEROSPACE LTD	Work Order:	44879	
Description: BUSHIN G-	Part Number:	D2617-1	
Inspection Dwg: D2417 Rev: D2		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
1.875	±.010	1.877	_			
.375	I, 0/0	.375				
.058	I,010	. Bon 057		<u> </u>		
·						
					·	
			·,		·	

Measured by:	ml	Audited by:	18	Prototype Approval:	N/A
. Date:	09/0/129	Date:	09/01/22	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	• •	New Issue	KJ/JLM	







ı	DESIG	м ВW	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
	CHEC	KED #	APPROVED!	DRAWING NO. REV. D
	DATE	r a	<u></u>	TITLE SCALE
	01.0)7.04		BUSHING 1:1
	Α		96.10.08	NEW ISSUE
	D		07.05.00	075 WAO 4 405

DZ 04.4.10 HP ADD 172617-7

A 96.10.08 NEW ISSUE


B 97.05.08 .875 WAS 1.125

C 97.06.04 0.369 DIA WAS 0.375

D 01.07.04 ADD MAT'L SPEC AND TOL./DIM. NOTE


DI CA.07.12 CORRECT TELERANCE (NCR 779)

 $D2617-1 (0.375 \text{ OD } \times 0.058 \text{ WALL})$



Whits 79


D2617-3 (0.375 OD x 0.058 WALL)



DZ DZL17-2 -> SAME AS DZ617-3 EXCEPT MAGE
FROM DELFIN (MODERN-R)

D2617-5 (0.500 OD x 0.058 WALL)





NOTES:

1) MATERIAL: 5052-H32 (QQ-A-225/7 OR WW-T-700/4)

OR 6061-T6 (QQ-A-225/8, QQ-A-200/8, OR WW-T-700/6)

- 2) BREAK ALL SHARP EDGES 0.005 TO 0.010
- 3) FINISH: ACID ETCH, ALODINE PER QSI 005 4.1
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 5) ALL DIMENSIONS ARE IN INCHES

Copyright @ 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.